

H3C switch cannot connect to Huawei optical fiber



Overview

On the H3C S7506 switch, configure the authentication mode in the view of OSPF area 0, that is, OSPF authentication-mode md5. Note: This case is for your reference only. The configuration is as follows: After the configuration is complete, the direct IP address can be pinged, and the message "ospf authentication failed" is displayed on the Huawei device. As a result, the OSPF neighbor relationship cannot be established. Check whether the passwords entered on the. A hybrid copper-fiber cable is a cable that integrates optical fibers and conductive copper wires. Perform a. The optical module is the electronic component of photoelectric conversion. Nowadays. Form a loop on the port using an optical fiber, and check whether the port can go Up (if optical modules with a long transmission distance are used, use optical attenuators. A combo interface is used but is.



Article Content

Checking the Optical Module Type

The optical module cannot be installed in an optical interface because the optical module structure is non-standard. The structure and size of some non-certified optical modules do not comply with the

Optical Module Solutions for Huawei S5700/S5720 Series Switches

Problem: All optical ports cannot be connected, and the indicator lights are not on.

Solution: To solve this problem, you can follow these steps: Check if the fiber and optical modules

An Optical Interface Cannot Go Up

Run the display transceiver command to check whether any alarms about the optical module are generated. If so, handle the problem based on alarm information. For example, if an alarm indicates

H3C S5560X-EI Switch Series Troubleshooting Guide-6W100

If fiber cables are used for IRF connection, verify that the peer transceiver modules are the same model and the fiber cables are connected correctly. QSFP+ to SFP+ cables cannot be used for IRF

Troubleshooting for Optical Modules on Huawei Switch

Check whether the optical module is Huawei-certified. If it is not certified by Huawei, replace it with a Huawei certified one. Remove and reinstall the optical module. ...

H3C Hybrid Copper-fiber Cable-H3C

Hybrid Copper-Fiber Cable (hereinafter referred to as hybrid cable) is a new type of cable that combines power transmission copper wires and data optical fibers, which can carry out long distance power

Troubleshooting for Optical Modules on Huawei Switch

When connecting switches through optical ports, pay attention to the following points: The optical modules used on both ends must have the same wavelength. The

Switches-H3C

H3C industrial switches can operate in -40°C - 75°C environments for a long time, and use industrial components to reach IP40 rating. At the same time, with shockproof, anti-electromagnetic

Port: Optical Ports on the AC Cannot Go Up

Use an optical fiber to perform a loopback test on the Huawei device. If the link goes Up, the Huawei device is working properly, and the fault may occur on the peer device or the link. Use an optical

A Huawei Switch Fails to Interconnect with H3C Switch Through

Solution On the H3C S7506 switch, configure the authentication mode in the view of OSPF area 0, that is, OSPF authentication-mode md5. After the configuration is complete, the OSPF neighbor

Typical Troubleshooting Cases of Optical Module

Possible causes include: The connector attenuation of the optical fiber exceeds the attenuation threshold, or the optical fiber is bent seriously. Install another optical module on the port and check

H3C All-Optical Network Technology White Paper-6W100

In contrast, the EPON-based POL solution leverages the EPON OLT's enhanced Ethernet forwarding and switching capabilities. iOptic network devices H3C provides an extensive array of iOptic Ethernet

Can original HUAWEI optical module be used on H3C

So can original HUAWEI optical module be used on H3C switch? The answer is No. Some companies, especially some famous companies, such as CISCO, HUAWEI

H3C S5130-HI Switch Series Troubleshooting Guide-6W101

H3C S5130 Series Switches, When you troubleshoot xxx, follow these general guidelines: · To help identify the failure cause, collect system and configuration information, including: ? Symptom, time of

04-Chapter 4 Connecting Your Switch to the Network

The 10/100Base-TX and 1000Base-T ports of the H3C S7500E switches use RJ-45 connectors and support MDI/MDI-X auto-sensing. Use category-5 twisted pair cables or above to connect the

How To Check If Interconnected Optical Ports Cannot

If the problem is not caused by the optical modules, fibers, or intermediate device, connect the switch to another interface or replace the switch to check whether the

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://www.blazingfast.co.za>

Email: info@blazingfast.co.za

Phone: +27 83 416 7295

Address: Plot 45, Silicon Savannah Road, Tatu City, Kiambu 00900, Kenya

This document is for informational purposes only. Specifications subject to change without notice.

